

UNIT NUMBER SWMU 116

UNIT NAME Rubble pile 14

REGULATORY STATUS: AOC

LOCATION: North bank of Big Bayou

APPROXIMATE DIMENSIONS: Approx. 20 ft by 50 ft

FUNCTION: Halt erosion at minor tributary run-off ravine entering Big Bayou

OPERATIONAL STATUS: In place

DATES OPERATED: Unknown

SITE/PROCESS DESCRIPTION: Concrete rubble placed in ravine going into Big Bayou

WASTE DESCRIPTION: Concrete rubble probably from PGDP road upgrading

WASTE QUANTITY: Approx. 30 cu yds

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Beta/Gamma and Soil Gamma surveys revealed no detectable contamination over background.

RFI NECESSARY: YES



